

#12ST-2 - DESCRIPTION

		RL	SN	K	FF
Started 5/12/75 (hold up) Top only - with bridge and braces					
Top PPG #23 -177.5 grams - .075K - 45° with hysol	.25 .50 1.0	.013/.012 .026/.025 .053/.051	.010/.007 .020/.016 .043/.036	.045	
<hr/>					
#12ST-3-4 7/7/75 a.m. Cut down brace sets #3 and #5 from .400" high at the bridge and to 2" above the bridge. They then taper northward to about .300". Brace sets #1, #3 and #5 are all about .300" at extreme north. - The K remained the same - .031 x 2 = .062 - Much improved - CHK. 7/7/75 p.m. Removed a very little from braces #1 and #2 at bridge level and south. - Now nothing is over .400". - The K jumped up to .065 - .0325 x 2 = .065 - Good compromise - quit - CHK. - Not as bright as 12ST-1.					
#12ST-2-3 7/3/75 All Trimmed fans to try to match numbers of 12ST-1. Trimmed North and South - not in bridge area.	.25 .50 1.0	.015/.017 .031/.032 .065/.065	.011/.009 .024/.018 .053/.026	.032 x 2 = .064	
#12ST-2-2 6/13/75 Removed sparkles. 6/17/75 No strings, patch on	.25 .50 1.0	.014/.014 .028/.028 .058/.057	.011/.010 .023/.022 .052/.048	.0245 x 2 = .049	
#12ST-2-1 6/6/75 Added sparkles.					