### Application of the problem of th		#39 - DESCRIPTION	ſ		1		
Model #1687-8, S/N 0039-98 60° — top #2 151.7 before holes Bridge 13.2 with finish — 16.2 w/retainer. Braces: 1 — 7.8 6 — 2.9 2 — 3.2 7 — 5.2 3 — 5.3 8 — 3.4 4 — 2.9 9 — 7.8 = \(\pi \). 9 = 7.8 = \(\pi \). 9 5 — 3.4 Bridge brace 4.2, .250" wide Top only with bridge, bridge brace, braces. Rim 86., medium. #39-2 8/3/76 Installed on bowl. #39-1 4/28/76 #2 recheck of top bridge and bridge brace. Note that #1 brace set was replaced yesterday. 50.014/.014 .010/.009 .064/.064 .014/.038 .041		,	=	RL	SN	K	FF
151.7 before holes Bridge 13.2 with finish — 16.2 w/retainer. Braces: 1 — 7.8 6 — 2.9 2 — 3.2 7 — 5.2 3 — 5.3 8 — 3.4 4 — 2.9 9 — 7.8 = ५६.९ 5 — 3.4 Bridge brace, braces. Rim 86., medium. #39-2 8/3/76 Installed on bowl. Has carbon splines on top of neck. #39-1 4/28/76 #2 recheck of top bridge and bridge brace. Note that #1 brace set was replaced yesterday. 5 — 0.030/.031 .020/.018 .041/.038 .041/.038 .041/.038 .041/.038 .041/.039 .059 .059 .064/.064 .044/.039 .0575 .098				2	٥		0
Rim 86., medium. #39-2 8/3/76 Installed on bowl. Has carbon splines on top of neck. #39-1 4/28/76 #2 recheck of top bridge and bridge brace. Note that #1 brace set was replaced yesterday. #39-1		151.7 before holes Bridge 13.2 with finish $-$ 16.2 w/retainer. Braces: $1-7.8$ $6-2.9$ $2-3.2$ $7-5.2$ $3-5.3$ $8-3.4$ $4-2.9$ $9-7.8 = 41.9$.50 1.0	.030/.031	.020/.018	.064	
#39-2 8/3/76 Installed on bowl. Has carbon splines on top of neck. #39-1 4/28/76 #2 recheck of top bridge and bridge brace. Note that #1 brace set was replaced yesterday. #39-1		Top only with bridge, bridge brace, braces.	17				
8/3/76 Installed on bowl. Has carbon splines on top of neck. #39-1 4/28/76 #2 recheck of top bridge and bridge brace. Note that #1 brace set was replaced yesterday. 25 .015/.015 .010/.009 .021/.019 .021/.019 .044/.039 .059 .064/.064 .044/.039 .059 .010/.010 .0575 ~98		Rim 86., medium.					
#39-1 4/28/76 #2 recheck of top bridge and bridge brace25 .014/.015 .010/.010 .0575 ~98 Note that #1 brace set was replaced yesterday50 .028/.029 .021/.020	340 5	8/3/76 Installed on bowl.	.50	.031/.031	.021/.019	.059	31
		#39-1 4/28/76 #2 recheck of top bridge and bridge brace.				.0575	~98
)	Note that #1 brace set was replaced yesterday.					
					100		
			22		30 C		
						50	
					# 11		
			- Mari				= 11
	y. •			20.00	N. S. W.		:
					ARREST TO THE STATE OF THE STAT		
							8
			5 1				¥1
					t,		
					2841		
	- 1						9=

TECHNICIAN DATE Offo/26 DESCRIPTION GUITAR NUMBER _____OO39 db 185 +15 +10 +5 572 0 -5 -10-15 -20-258372. 9000. REF 9397.2 Hz 30. REF 6271.8 7040. 587.3 146.8 164.8 293.7 659.3 1046.5 2349.3 4698.6 261.6 329.6 523.3 1174.7 1318.5 784. 196. 220. 392. 440. 880. 1568. 1760. 2093. 2637. 3136. 3520. 4186. A G F D C U П ш о ч о ш O A o 4 ပ O A Ç