#72 - DESCRIPTION

	#72 – DESCRIPTION					
	12/14/70	6	RL	SN	К	FF
	Model #1687-7, S/N 0072- new core Top only with bridge, bridge brace, braces. 60° Top #42 165.2 before holes Bridge 12.3 with finish $-$ 15.3 w/retainer. Braces: $1-8.2$ $6-2.6$ $2-3.3$ $7-5.8$ $3-5.8$ $8-3.3$ $4-2.6$ $9-8.2$ $5-4.3$ Bridge brace 5.0 Total 233.6 weighed	.25 .50 1.0	•	.008/.009 .016/.017 .034/.034	.055	
÷	#72- 11/30/77 Top weight heavy by 5.2 grams (165.2) R - loose by .006 L - loose by .004 piece of #5 removed S - loose by .003 neck bowed N - loose by .001 K - loose by .005	for pt	tant cal		24	
	We could lightly fill the rim with laminac which stiffened R/L/S/K (see note on 29). We could add carbon to #1 and a small amount to #5 in South, or add finger to finger. We could add carbon to Br.Br. Δ 7, 6, 4, 4, 7. We could add carbon to #1 and anchor #5 to heel block.				÷	
	#72-3 9/13/77 Measured. Everything became tighter in spite of filing #4 and 6.	.25 .50 1.0	1	.010/.008 .020/.017 .041/.035	.070	
	#72-3 9/8/77 Filed #4 and 6 in the South to try to bring the south reading nearer to .045. Not measured this date. Neck was bowed — impossible to straighten. Bass was 5 — went to 4 Treble was 4 — went to 3	£.	9 6: 8:	ta W	#5	
	#72-2 9/8/77 Filed #1 set from bridge South. Sound improved particularly in B & E strings.	.25 .50 1.0		.010/.009 .020/.018 .042/.036 ∆ 2 same	.072 ∆ 11	
	· (continued)	ra .	:		
		:				
						10.

